



www.tysol.com

TY-SPRAY Low Residue Powder

Chemistry designed for spray cabinets and automatic wash systems. Formulated to attack dirt, oil and heavy grease.

SAFE ON ALL METALS

Low Residue Powder is our premium powdered alkaline, foam controlled detergent. For use in spray cabinets and automatic wash systems for cleaning parts and equipment where a residue free surface is required.

- Safe on multiple metal surfaces including aluminum and alloys.
- Safe on most painted surfaces, plastic or rubber parts.
- Attacks and destroys carbon, heavy grease, lube oils and soils.
- Controls foam build-up at warm operating temperatures above 135° F.
- Rinses freely with water to provide a residue free part.

USE INSTRUCTIONS:

Low Residue Powder can be used at 4 ounces per 1 gallon of hot water. Place the product on the cabinet floor and close the cabinet door completely. Activate sprayers for about three minutes to dissolve the cleaner. Concentration can be monitored by the use of an alkalinity titration kit. The temperature range recommended for cleaning is 135° - 190° F, typically for 5 to 30 minutes.

TECHNICAL DATA:

pH (use dilution).....	Approximately 11.5 to 12
pH (10%).....	12.5 to 13
Color.....	Off-white
Rinseability.....	Excellent